

$ZS$  is normal to  $CD$ , so its equation can be written and solved simultaneously with that of the line  $CD$  to find the coordinates of point  $S$  and the length  $ZS$ , which are

$$\begin{aligned}\sigma'_{m@S} &= \frac{S_{ut}(S_f^2 - S_f\sigma'_a + S_{ut}\sigma'_m)}{S_f^2 + S_{ut}^2} \\ \sigma'_{a@S} &= -\frac{S_f}{S_{ut}}(\sigma'_{m@S}) + S_f \\ ZS &= \sqrt{(\sigma'_m - \sigma'_{m@S})^2 + (\sigma'_a - \sigma'_{a@S})^2}\end{aligned}\quad (6.18f)$$

To establish a ratio for the safety factor, swing point  $S$  about point  $Z$  to be coincident with line  $OZS'$  at point  $S'$ . The safety factor is the ratio  $OS'/OZ$ .

$$\begin{aligned}OZ &= \sqrt{(\sigma'_a)^2 + (\sigma'_m)^2} \\ N_f &= \frac{OZ + ZS}{OZ}\end{aligned}\quad (6.18g)$$

There is also the possibility that point  $S$  may lie on line  $DE$  instead of  $CD$ , in which case equation 6.16d (p. 384) should be substituted for 6.16c in the above solution.

Case 4 gives a more conservative safety factor than case 3. The same approach can be used to obtain safety-factor expressions for stress-component combinations in the left half-plane of the modified-Goodman diagram. Also, if the diagram is drawn to scale, rough estimates of the safety factors can be scaled from it. The *TKSolver* file GOODMAN supplied with this text calculates all the safety factors defined in equations 6.18 (p. 388) for any supplied values of  $\sigma'_a$  and  $\sigma'_m$ , and it plots the modified-Goodman diagram and the stress line  $OZ$  extended so that the failure intercept can be seen.

### Design Steps for Fluctuating Stresses

A set of design steps similar to those listed for the fully reversed case can be defined for the case of fluctuating stresses:

- 1 Determine the number of cycles of loading  $N$  that the part will experience over its expected service life.
- 2 Determine the amplitude of the applied alternating loads (mean to peak) and of the mean load. (See Chapter 3 and equations 6.1, p. 329.)
- 3 Create a tentative part-geometry design to withstand the applied loads based on good engineering practice. (See Chapters 3 and 4.)
- 4 Determine any geometric stress-concentration factors  $K_t$  at notches in the part's geometry. Try, of course, to minimize these through good design. (See Section 4.15 on p. 193.)